

# WATER WELL REPORT

STATE OF WASHINGTON

Application No. **G1-25152**

Permit No. **000049**

(1) OWNER: Name **CAMBANO VISTA W/DIST** Address \_\_\_\_\_

(2) LOCATION OF WELL: County **ISLAND** **S 1/4 Sec. 10 T 30 N. R 35 W.M.**  
Bearing and distance from section or subdivision corner **WELL #6**

(3) PROPOSED USE: Domestic ☐ Industrial ☐ Municipal ☐  
Irrigation ☐ Test Well ☐ Other ☒

(4) TYPE OF WORK: Owner's number of well (if more than one) **#6**  
New well ☒ Method: Dug ☐ Bored ☐  
Deepened ☐ Cable ☐ Driven ☐  
Reconditioned ☐ Rotary ☒ Jetted ☐

(5) DIMENSIONS: Diameter of well **6** inches.  
Drilled **280** ft. Depth of completed well **280** ft.

## (6) CONSTRUCTION DETAILS:

Casing installed: " Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Threaded ☐ " Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Welded ☒ **6** " Diam. from **+2** ft. to **275** ft.

Perforations: Yes ☐ No ☒  
Type of perforator used \_\_\_\_\_  
SIZE of perforations \_\_\_\_\_ in. by \_\_\_\_\_ in.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Screens: Yes ☒ No ☐  
Manufacturer's Name **JOHNSON**  
Type **SS** Model No. \_\_\_\_\_  
Diam. \_\_\_\_\_ Slot size \_\_\_\_\_ from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Diam. **5/8** Slot size **0.15** from **115** ft. to **280** ft.

Gravel packed: Yes ☐ No ☒ Size of gravel: \_\_\_\_\_  
Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Surface seal: Yes ☒ No ☐ To what depth? **18** ft.  
Material used in seal **Bentonite**  
Did any strata contain unusable water? Yes ☐ No ☒  
Type of water? \_\_\_\_\_ Depth of strata \_\_\_\_\_  
Method of sealing strata off \_\_\_\_\_

(7) PUMP: Manufacturer's Name **GRUNDIGS**  
Type **Sub** HP **3**

(8) WATER LEVELS: Land-surface elevation **222.26** ft.  
Static level **222** ft. below top of well Date \_\_\_\_\_  
Artesian pressure \_\_\_\_\_ lbs. per square inch Date \_\_\_\_\_  
Artesian water is controlled by \_\_\_\_\_ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level  
Was a pump test made? Yes ☒ No ☐ If yes, by whom? **DRILLER**  
Yield: **39** gal./min. with **2.6** ft. drawdown after **4** hrs.  
" " " " " " " " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test \_\_\_\_\_  
Bailer test \_\_\_\_\_ gal./min. with \_\_\_\_\_ ft. drawdown after \_\_\_\_\_ hrs.  
Artesian flow \_\_\_\_\_ g.p.m. Date \_\_\_\_\_  
Temperature of water \_\_\_\_\_ Was a chemical analysis made? Yes ☒ No ☐

## (10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
TAN CLAY & SAND	0	35
SAND & GRAVEL	35	190
BLUE CLAY	190	217
SILT & SAND	217	226
BLUE CLAY	226	258
SILT & SAND w/wood	258	262
BLUE CLAY	262	266
SAND GRAVEL w/WATER	266	280

RECEIVED

JAN 14 1988

DEPARTMENT OF ECOLOGY  
NORTHWEST REGION

Work started **11-6**, 19**87**. Completed **11-8**, 19**87**

## WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME **CAMBANO WELL DRILLING**  
(Person, firm, or corporation) (Type or print)

Address **215 N. 600 DRICH RD**

[Signed] **William J. Kelley**  
(Well Driller)

License No. **1525** Date **12 -**, 19**87**